

08487-06 APR 64

SECRET

TO 25X1 DIRECTOR

FROM

25 YEAR RE-REVIEW

ACTION:

INFO :

OPS 1-8

PRIORITY

TOR 1232Z 06 APR 64

IN-71764

TO

25X1

[Redacted]

1437

25X1

S154A 060200Z

25X1

[Redacted]

1. 723, 37

2. 100

3. NORMAL OPERATION

25X1

[Redacted]

1. 701, 705, 50, 9, 52, 13, 1016, 1002

2. 100

3.0 SOME 400 CYCLE NOISE ON L-BAND

25X1

[Redacted]

1. 2

2. NO ACTIVITY

25X1

[Redacted]

1. 1, 4, 2, 4

2. NO ACTIVITY

RADIO AND NAVAIDS SATISFACTORY

BIRDWATCHER SN3

SECRET

GROUP 1
Excluded from automatic
downgrading and
declassification



7 (IN-71764)

S E C R E T

PAGE TWO

NORMAL OPERATION EXCEPT AT 20 MINUTES AFTER TAKE OFF WHEN
THE PILOT PUSHED ALL OK THE SECOND CHIRP HAD A HOLE IN THE
CENTER OF THE TRANSMISSION AND THE THIRD CHIRP WAS VERY SHORT.
OTHER THAN THIS ALL CHIRPS WERE NORMAL AND FULL DURATION.

END OF MESSAGE

S E C R E T